

석면비산측정 결과보고서

- 2013,2015년 염전생산시설(창고,해주)슬레이트처리사업 -

[별 첨1] 측정 위치도(측정 장소)

2013,2015년 염전생산시설(창고,해주)슬레이트처리사업



편 례	*NO	
	시료채취	부지경계선

[별첨2] 측정 결과

측정위치		측정시간(분)	유량(l/min)	측정농도 [기준: 0.01개/cm ³]	초과여부
*1	부지경계1	9:10 ~ 13:12	10.0	불검출[검출한계 0.002미만]	미만
*2	부지경계2	9:15 ~ 13:17	10.0	불검출[검출한계 0.002미만]	미만
*3	부지경계3	9:20 ~ 13:22	10.0	불검출[검출한계 0.002미만]	미만
*4	부지경계4	9:25 ~ 13:27	10.0	불검출[검출한계 0.002미만]	미만
*5	작업장주변	9:55 ~ 11:57	10.0	불검출[검출한계 0.002미만]	미만
*6	폐기물반출구	14:10 ~ 14:52	10.0	불검출[검출한계 0.002미만]	미만
*7	위생설비입구	14:22 ~ 15:04	10.0	불검출[검출한계 0.002미만]	미만

[별첨3] 측정 사진

			
*1. 부지경계선	*2. 부지경계선	*3. 부지경계선	*4. 부지경계선
			-
*5. 작업장 주변	*6. 폐기물반출구	*7. 위생설비입구	-